

MMMX/MEX STAR RWYS 05L/R

MEXICO CITY, MEXICO




ARRIVALS RWYS 05L/R

VIVER ONE ALFA (VIVER1A), LIBOR ONE ALFA (LIBOR1A)



MMMX_APP 121.2
ATIS 127.65



(NARRATIVE ON FOLLOWING PAGE)

NOTE: DME and RADAR required, chart not to scale

ARRIVAL DESCRIPTION

VIVER ONE ALFA (VIVER1A), LIBOR ONE ALFA (LIBOR1A)

VIVER ONE ALFA (VIVER1A): check MEX VOR at FL280, then descend and maintain FL250 proceed on MEX radial 311 to D15 MEX, then SLM 14 DME ARC, check before or at D3 SLM VOR at 16,000, then turn right to intercept SLM R-218 to SMO, descend to and cross SMO VOR at 11,000 expect clearance to proceed with approach procedure

LIBOR ONE ALFA (LIBOR1A): check MEX VOR at FL280, then descend and maintain FL250 proceed on MEX radial 311 to D15 MEX, then SLM 14 DME ARC, check before or at D3 SLM VOR at 16,000, then turn right to intercept SLM R-218 to SMO, descend to and cross SMO VOR at 11,000 expect clearance to proceed with approach procedure

NOTE: Arrival instructions can be change in accordance with ATC



MMMX/MEX STAR RWYS 23L/R

MEXICO CITY, MEXICO




ARRIVALS RWYS 23L/R



VIVER ONE BRAVO (VIVER1B), LIBOR ONE BRAVO (LIBOR1B)

MMMX_APP 121.2
ATIS 127.65



(NARRATIVE ON FOLLOWING PAGE)

NOTE:DME and RADAR required, chart not to scale

ARRIVAL DESCRIPTION

VIVER ONE BRAVO (VIVER1B), LIBOR ONE BRAVO (LIBOR1B)

VIVER ONE BRAVO (VIVER1B): check MEX VOR at FL280, then descend and maintain FL250 proceed on MEX radial 311 to D15 MEX, then SLM 14 DME ARC, check SLM VOR at 16,000, continue on SLM R-138 descend and maintain 12,000 to D8 SLM expect clearance to proceed with approach procedure

LIBOR ONE BRAVO (LIBOR1B): check MEX VOR at FL280, then descend and maintain FL250 proceed on MEX radial 311 to D15 MEX, then SLM 14 DME ARC, check SLM VOR at 16,000, continue on SLM R-138 descend to maintain 12,000 to D8 SLM expect clearance to proceed with approach procedure

NOTE: Arrival instructions can be change in accordance with ATC

